	IHC CD)F Dredge Pr	oject : Air I	Monitoring A	larm Response Log
Air Monitoring Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:					
Cerex Unit (Naphthalene) I Thermo Unit (Pa		articles)	□ PID Monitor		
Date & Time of alarm: <u>5/14/2015 2:30 AM</u>			Email sent	to site Technician?	(Yes or No)
Technician responded to the alarm; Scott Peterson					
 Was dredging occurring at the time of the alarm? Alarm caused by: 					(Yes) or No)
Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube Air Quality X Other:					
3. Corrective Actions taken?				(Yes or No))	
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

A) No problems were found.