	IHC CDF	Dredge Pr	oject : Air I	Monitoring A	larm Response Log	
Air Monitoring Station:	□ M1	□ M2	X M3	□ M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene) I Thermo Unit (Par			articles)	□ PID Monitor		
Date & Time of alarm: <u>5/24/2015 8:45-2:00</u>			Email sent	to site Technician?	(Yes or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?				(Yes or No)		
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other:						
					_	
3. Corrective Actions taken?				(Yes or No)		
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

Description of Action Taken:

A) No problems found wrong with the air unit.