## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitori	ing S	tation:	☐ M1	☑ M2	☑ M3	□ M4	□ Dock
Air Monitoring Instrument:							
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Partic					les)	☐ PID Monitor	r
Date & Time of alarm: <u>6/12/2015 3:00 AM</u>					Email sent to si	te Technician?	(Yes or No)
Technician responded to the alarm; Scott Peterson							
1. Was dredging occurring at the time of the alarm?							(Yes) or No)
2. Alarm caused by:							
	]	Loss of Power					
_	]	Loss of Radio Communication					
_	X	Out of Calibration	on				
	1	UV Alignment					
	Blockage in Air Tube						
		Air Quality					
-	X	Other: weather					
L							
3. Corrective Actions taken?						(Yes or No)	
4. Dredging suspended?						(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?							(Yes) or No)

## Description of Action Taken:

A) No problems were found wrong with the air unit. A quick check of the calibration was performed however all system appeared normal.