IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Mo	onitoring	Station:	□ M1	□ M2	☑ M3	□ M4	□ Dock
Air Monitoring Instrument:							
☐ Cerex Unit (Naphthalene)					cles)	☐ PID Monito	r
Date & Time of alarm: 7/7/2015 5:30AM Email sent to site Technician							(Yes or No)
Technician responded to the alarm; Scott Peterson							
1.	Was dred	dging occurrin	g at the time	of the alarm?			(Yes or No)
2.	2. Alarm caused by:						
		Loss of Powe	er				
		Loss of Radio	o Communic	ation			
		Out of Calibr	ation				
		UV Alignmen	nt				
		Blockage in A	Air Tube				
		Air Quality					
	X	Other: Weath	ier				
3.	3. Corrective Actions taken?						(Yes or No)
4.	4. Dredging suspended?						(Yes or No)
5.	Alarm lo	gged in air mo	onitoring acti	ion spreadsheet?			(Yes) or No)

Description of Action Taken:

A) No problems found wrong with the air unit. Video camera records were reviewed. Storms just started when air unit alarmed.