IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Sta	ation:	□ M2	X M3	□ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Nap	ohthalene)	☑ Thermo Uni	t (Particles)	☐ PID Monito	or
Date & Time of alarm: <u>7/12/2015 4:15AM</u>			Email s	ent to site Technician?	(Yes or No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Le	oss of Power				
L	oss of Radio Comm	unication			
0	ut of Calibration				
U	V Alignment				
Blockage in Air Tube					
A	ir Quality				
X O	ther: Weather				
					_
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

A) No problems found wrong with the air unit. Video camera records were reviewed. There were storms and light winds when air unit alarmed.