IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	X M2	X M3	□ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene)	\mathbf{x}	Thermo Unit (Par	ticles)	☐ PID Monito	or
Date & Time of alarm: <u>9/18/2015 5:45PM-7:00</u> PM			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Pow	er				
Loss of Rad	Loss of Radio Communication				
Out of Calib	Out of Calibration				
UV Alignme	ent				
Blockage in	Blockage in Air Tube				
X Air Quality	X Air Quality				
X Other: Weat	her, Rain, Th	understorms			
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

The reason for the air alarm is unknown maybe weather related. Air unit calibration was checked and is with-in tolerance.