IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring S	Station:	M1	□ M2	□ M3	□ M4	☐ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Par				Particles)	☐ PID Monito	or
Date & Time of alarm: <u>10/8/2015 9:45-3:15</u>				Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Power					
	Loss of Radio Communication					
	Out of Calibrati	on				
	UV Alignment					
	Blockage in Air	Tube				
X	Air Quality					
X	Other: dry cond	itions				
3. Corrective Actions taken?					(Yes) or No)	
4. Dredging suspended?						(Yes or No)
5. Alarm log	5. Alarm logged in air monitoring action spreadsheet?					

Description of Action Taken:

USACE maintenance personnel are preforming repairs to the roadway on the east cell. Trucks carrying stone and dirt are kicking up dust from the gravel roads. Lead operator notified the truck drivers to slow down while driving on the site.

