## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	X M2	□ M3	□ M4	□ Dock
<b>Air Monitoring Instrument:</b>					
☐ Cerex Unit (Naphthalene)			Particles)	☐ PID Monitor	
Date & Time of alarm: 03/24	/2016		Email sent	to site Technician?	(Yes)or No)
Technician responded to the a	larm; Scott Pe	eterson			
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Pow	ver				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: unkn	own				
3. Corrective Actions taken?					(Yes or No
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

## Description of Action Taken:

There was no reason found for the air unit alarm. At the time of the alarm, no personal was on site. Site security video log were reviewed. The unit was checked the next day and are within calibration ranges.