		IHC CD	F Dredge Pr	oject : Air I	Monitoring A	larm Response Log
Air Monitoring	-	X M1	区 M2	🖾 M3	□ M4	Dock
Air Monitoring Instrument:□ Cerex Unit (Naphthalene)Image: Image: Image				articles)	□ PID Monite	٦r
Date & Time of alarm: <u>06/13/2016 9:30 pm</u>				Email sent to site Technician? (Yes)or No)		
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
	Loss of Powe	er				
	Loss of Radio Communication					
	Out of Calibration					
	UV Alignment					
Blockage in Air Tube						
	Air Quality					
X	Other: weath	er				
3. Corrective Actions taken?						(Yes or No
4. Dredging suspended?						(Yes or No))
5. Alarm logged in air monitoring action spreadsheet?						(Yes) or No)
Description of Action Taken:						

## Description of Action Taken:

No reason found for the air unit to alarm.