IHC CDF Dredge Project : Air Monitoring Alarm Response Log					
Air Monitoring Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:					
□ Cerex Unit (Naphthalene)			articles)	\Box PID Monito	or
Date & Time of alarm: <u>09/15/16 12:45AM</u>			Email sent	Email sent to site Technician? (Yes) or No)	
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?				(Yes) or No)	
2. Alarm caused by:					
Loss of Power					
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: Unk	nown				
3. Corrective Actions taken?					(Yes or No
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

The air unit nephelometer was found out of calibration. Unit was re-calibrated. On 9/16/2016 a small spider was vacuumed out of the nephelometer filter paper, the nephelometer was recalibrated.