IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene)			articles)	☐ PID Monitor	
Date & Time of alarm: <u>10/14/16 1:15AM</u>			Email sent	to site Technician?	(Yes) or No)
Technician responded to the a	larm; Scott Pe	eterson			
1. Was dredging occurring at the time of the alarm?					(Yes) or No)
2. Alarm caused by:					
Loss of Pow	er				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: Smal	l spider				
3. Corrective Actions taken?					(Yes or No
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

Inlet tube was cleaned and inspectioned. Small spiders were found in naphalometer filter. Air units calibrations were checked.