IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	X M2	□ M3	□ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene)			Particles)	☐ PID Monitor	
Date & Time of alarm: <u>11/02/16 11:15AM</u>			Email sent	to site Technician?	(Yes or No)
Technician responded to the a	larm; Scott Pe	eterson			
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Pow	er				
Loss of Rad	Loss of Radio Communication				
Out of Calib	ration				
UV Alignme	ent				
Blockage in Air Tube					
X Air Quality					
X Other: Weat	her				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

Air units calibrations were checked and with-in toloarnce.