	IHC CD	F Dredge Pr	oject : Air	Monitoring A	larm Response Log	
Air Monitoring Sta Air Monitoring Ins		X M2	□ M3	□ M4	Dock	
Cerex Unit (Naphthalene)			articles)	icles)		
Date & Time of alarm: <u>1/03/17 7:30AM</u>			Email sent	to site Technician?	(Yes)or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
Lo Ou UV Bla X Air	ss of Power ss of Radio Communic at of Calibration / Alignment ockage in Air Tube r Quality her: Weather	ation				
3. Corrective Actions taken?					(Yes) or No)	
4. Dredging suspended?					(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	
Description of Action Taken:						

Droin

- -

-

AirMa

-

.....

Log

ILC CDE Dro

Air units calibrations were checked and with-in toloarnce.