	IHC CD	F Dredge Pi	roject : Air	Monitoring	g Alarm Response Log	
Air Monitoring Station: Air Monitoring Instrume	□ M1 nt:	🖾 M2	□ M3	□ M4	□ Dock	
Cerex Unit (Naphthalene)			articles)	ticles)		
Date & Time of alarm: <u>1/</u>		Email sent	to site Technicia	an? (Yes)or No)		
Technician responded to the	e alarm; Scott Pe	eterson				
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
Out of Ca UV Align	Radio Communica alibration nment e in Air Tube ity	ation				
3. Corrective Actions taken?					(Yes) or No)	
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	
Description of Action To	aken:					

Droin

- -

-

AirMa

-

.....

Log

ILC CDE Dro

Air units calibrations were checked and with-in toloarnce.