IHC CDF Dredge Project : Air Monitoring Alarm Response Log					
Air Monitoring Station: Air Monitoring Instrument:	□ M1	X M2	□ M3	□ M4	□ Dock
Cerex Unit (Naphthalene)			articles)	□ PID Monitor	
Date & Time of alarm: 2/07/17 5:45AM Email sent to site Technician?					(Yes or No)
Technician responded to the a 1. Was dredging occurri 2. Alarm caused by: Loss of Pow Loss of Rad Out of Calil UV Alignm Blockage in X X Other: Wear	ng at the time ver lio Communic pration ent Air Tube	of the alarm?			(Yes or No)
3. Corrective Actions taken?					(Yes) or No)
 4. Dredging suspended? 5. Alarm logged in air monitoring action spreadsheet? Description of Action Taken:					(Yes or No) (Yes)or No)

Description of Action Taken:

Air units calibrations were checked and with-in toloarnce.