IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	X M1	X M2	□ M3	□ M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			articles)	□ PID Monitor		
Date & Time of alarm: <u>5/23/2017 5:00PM</u>			Email sent	to site Technician?	(Yes or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other: weather	er, high winds	5				
3. Corrective Actions taken?				(Yes or No)		
4. Dredging suspended?					(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

Description of Action Taken:

A) No problems were found with air monitors. All air unit parameters were with-in tolorance during calibration check.