IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	□ M1	□ M2	□ М3	X M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			rticles)	□ PID Monitor		
Date & Time of alarm: <u>6/26/2017 to 6/28/2017</u>			Email sent	to site Technician?	(Yes)or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?				(Yes or No)		
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other: spider	S					
3. Corrective Actions taken?					(Vac or No	
					(Yes or No)	
4. Dredging suspended?					(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

## Description of Action Taken:

A) Small spiders and insects were found on the nephelometer filter paper. The air unit was cleaned sereval times to remove all the insects. Unit was recalibrated and checked again on June 30<sup>th</sup>.