\square M1 \square M2 \square M3 X M4 □ Dock **Air Monitoring Station: Air Monitoring Instrument:** ☐ Cerex Unit (Naphthalene) X Thermo Unit (Particles) ☐ PID Monitor Date & Time of alarm: <u>7/9/2017 to 7/10/2017</u> Email sent to site Technician? (Yes)or No) Technician responded to the alarm; Scott Peterson (Yes or No 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration **UV** Alignment Blockage in Air Tube Air Quality Other: spiders 3. Corrective Actions taken? (Yes or (No 4. Dredging suspended? (Yes or (No))

IHC CDF Dredge Project: Air Monitoring Alarm Response Log

((Yes) or No)

Description of Action Taken:

5. Alarm logged in air monitoring action spreadsheet?

A) Small spiders were found on the nephelometer filter paper. The air unit was cleaned to remove the insects. Unit was recalibrated and checked again on July 13th.