IHC CDF Dredge Project : Air Monitoring Alarm Response Log X M2 **Air Monitoring Station:** \Box M1 \Box M3 \Box M4 Dock Air Monitoring Instrument: □ Cerex Unit (Naphthalene) X Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: <u>7/31/2017 3:30PM</u> Email sent to site Technician? (Yes)or No) Technician responded to the alarm; Scott Peterson (Yes or No) 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube Air Quality Other: Spiders Х 3. Corrective Actions taken? (Yes or No 4. Dredging suspended? (Yes or No) ((Yes) or No) 5. Alarm logged in air monitoring action spreadsheet?

Description of Action Taken:

A) No Problems were found with air monitor. M2 air unit parameters were within tolerance during calibration check.