IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring	Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (N	X T	☑ Thermo Unit (Particles)		☐ PID Monitor		
Date & Time of alarm: <u>8/19/2017 to 8/21/2017</u>				Email sent to s	ite Technician?	(Yes)or No)
Technician responded to the alarm; Damian Allen						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Power					
	Loss of Radio Communication					
X	Out of Calibra	tion				
	UV Alignment	į				
	Blockage in Air Tube					
	Air Quality					
	Other: Spiders					
						_
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet? (Yes)						(Yes) or No)

Description of Action Taken:

A) M4 air unit parameters were reprogrammed and calibration was performed.