## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

<b>Air Monitoring Station:</b>	$\square$ M1	□ M2	□ M3	☑ M4	□Dock
Air Monitoring Instrum	ent:				
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa			articles)	☐ PID Monito	or
Date & Time of alarm: <u>10/16/2017</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm; Damian Allen					
1. Was dredging occurring at the time of the alarm?					(Yes) or No)
2. Alarm caused by:					
Loss of 1	Power				
Loss of	Loss of Radio Communication				
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: V	Vind, Insects				
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

## Description of Action Taken:

A) All air unit parameters were within tolerance during calibration check.