IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Station	:	☑ M2	□ M3	□ M4	□ Dock
Air Monitoring Instrum	nent:				
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa			articles)	☐ PID Monitor	
Date & Time of alarm: <u>9/17-21/2018</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm; Damian Allen					
1. Was dredging occurring at the time of the alarm?					(Yes) or No)
2. Alarm caused by:					
Loss of	f Power				
Loss of	Loss of Radio Communication				
Out of	Out of Calibration				
UV Al	UV Alignment				
Blockage in Air Tube					
Air Quality					
X Other:	Insects				
					_
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

A) Units were checked and cleaned from debris/insects. Units resumed operating within parameters.