IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitorin	ng Station:	X M1	X M2	□ M3	□ M 4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene)			Thermo Unit (P	articles)	☐ PID Monito	or
Date & Time of alarm: <u>6/19/19</u> 1:15 7:30			Email sent	to site Technician?	(Yes or No)	
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Powe	er				
	Loss of Radio Communication					
	Out of Calibr	ation				
	UV Alignme	nt				
	Blockage in Air Tube					
	Air Quality					
X	Other: weath	er				
						_
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)	

Description of Action Taken:

Alarms were caused by thunderstorms. M1 & M2 air units were checked the next morning