IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	□ M2	□ M 3	⋈ M4	□ Dock
Air Monitoring Instrument	:				
☐ Cerex Unit (Naphthalene)	X	Thermo Unit (P	articles)	☐ PID Monito	or
Date & Time of alarm: 7/3/19	9 5:15		Email sent	to site Technician?	(Yes or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Pov	wer				
Loss of Rac	Loss of Radio Communication				
Out of Cali	Out of Calibration				
UV Alignm	UV Alignment				
Blockage in Air Tube					
Air Quality					
X Other: Unk	nown				
					_
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

Description of Action Taken:

No problems were found wrong with the air unit. M4 air unit was recalibrated and checked again the next morning.