## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitorin	g Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Part			articles)	☐ PID Monito	or	
Date & Time of alarm: 7/14/19 1:45 am				Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Powe	er				
	Loss of Radio	o Communio	cation			
	Out of Calibr	ation				
	UV Alignme	nt				
Blockage in Air Tube						
	Air Quality					
X	Other: unkno	wn				
3. Corrective Actions taken?					(Yes or No	
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)	

## Description of Action Taken:

Air unit was recalibrated. Maybe a small spider in inlet tube? Inlet tube was vacuumed out but did not find any insects or debris.