IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Stat	tion:	□ M2	□ M3	☑ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Parti			ticles)	☐ PID Monito	or
Date & Time of alarm: <u>7/16/19 5:45 PM</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Lo	ess of Power				
Los	Loss of Radio Communication				
Ou	t of Calibration				
UV	√ Alignment				
Blockage in Air Tube					
Aiı	Air Quality				
X Otl	her: unknown				
3. Corrective Actions taken?				(Yes or No	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?				(Yes)or No)	

Description of Action Taken:

Air unit was recalibrated. Inlet tube was vacuumed out but did not find any insects or debris. Lawn maintenance was performed during the week.