## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monito	ring Station:	□ M1	☑ M2	□ <b>M</b> 3	□ <b>M</b> 4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene) ☐ Thermo Un			Thermo Unit (Pa	articles)	☐ PID Monito	or
Date & Time of alarm: <u>8/4/19 11:30 AM</u>				Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Pow	er				
	Loss of Rad	io Communic	ation			
	Out of Calib	oration				
	UV Alignm	ent				
	Blockage in Air Tube					
	Air Quality					
	X Other: unkn	own				
						_
3. Corrective Actions taken?					(Yes or No	
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?						(Yes)or No)

## Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units.