## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Statio	<b>n:</b> □ M1	□ M2	<b>X</b> M3	□ <b>M</b> 4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphth	alene)	Thermo Unit (Pa	articles)	☐ PID Monito	or
Date & Time of alarm: <u>8/6/19</u> 7:30 pm			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss	of Power				
Loss	Loss of Radio Communication				
Out o	Out of Calibration				
UV A	lignment				
Block	Blockage in Air Tube				
Air Q	Air Quality				
X Other	X Other: unknown, no activity on site during alarm				
3. Corrective Actions taken?				(Yes or No	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?				(Yes)or No)	

## Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units.