IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring	g Station:	□ M1	□ M2	X M3	☑ M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene)			articles)	☐ PID Monito	or	
Date & Time of alarm: 9/5 3:30 pm				Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Power	r				
	Loss of Radio	Communica	tion			
	Out of Calibra	ation				
	UV Alignmen	nt				
Blockage in Air Tube						
	Air Quality					
X	Other: unknow	wn				
3. Corrective Actions taken?					(Yes) or No)	
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units. Maybe weather related.