IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	□ M2	□ M3	☑ M4	□ Dock
Air Monitoring Instrume	nt:				
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (articles)	☐ PID Monito	or
Date & Time of alarm: <u>9/14 3:30 pm</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of F	ower				
Loss of F	Loss of Radio Communication				
Out of Ca	Out of Calibration				
UV Align	UV Alignment				
Blockage in Air Tube					
Air Qual	Air Quality				
X Other: ur	ıknown				
3. Corrective Actions taken?				(Yes) or No)	
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units.