IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	☑ M1	X M2	⊠ M3	X M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa		articles)	☐ PID Monitor		
Date & Time of alarm: 9/2	0 7:30 am		Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of I	Power				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: w	eather				
<u> </u>					
3. Corrective Actions taken?				(Yes)or No)	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

Description of Action Taken:

Thunderstorms during the morning.