IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring	Station:	□ M1	□ M2	X M3	X M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene)			articles)	☐ PID Monito	or	
Date & Time of alarm: <u>10/24 1:00 pm</u>				Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Power					
	Loss of Radio	Communica	tion			
	Out of Calibra	tion				
	UV Alignmen	t				
Blockage in Air Tube						
	Air Quality					
X	Other: unknow	vn				
	J					
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

Description of Action Taken:

No problems found during air monitor inspection. There is heavy traffic on site do to Kokosing Construction demobbing and Schwartz Excavation dump trucks off-loading dirt into west cell.