IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	□ M2	X M3	X M4	□ Dock
Air Monitoring Instrumen	nt:				
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa			articles)	☐ PID Monite	or
Date & Time of alarm: <u>10/25 11:45, 3:30, 4:15</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to the	e alarm? Scott P	eterson			
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Po	ower				
Loss of R	Loss of Radio Communication				
Out of Ca	Out of Calibration				
UV Align	ment				
Blockage	Blockage in Air Tube				
Air Quali	ty				
X Other: un	known				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

Description of Action Taken:

No problems found during air monitor inspection. There is heavy traffic on site do to Kokosing Construction demobbing and Schwartz Excavation dump trucks off-loading dirt into west cell.