IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monit	oring	Station:	□ M1	□ M2	□ M 3	X M4	□ Dock
Air Monitoring Instrument:							
☐ Cerex Unit (Naphthalene)					ricles)	☐ PID Monito	or
Date & Time of alarm: 1/24/20 4:00 PM Email sent to						to site Technician?	(Yes)or No)
Technician responded to the alarm? Scott Peterson							
1. Was dredging occurring at the time of the alarm?							(Yes or No)
2. Alarm caused by:							
		Loss of Powe	er				
		Loss of Radio	o Communio	cation			
		Out of Calibr	ration				
		UV Alignme	nt				
		Blockage in A	Air Tube				
		Air Quality					
	X	Other: unkno	wn				
							_
3. Corrective Actions taken?						(Yes or No)	
4. Dredging suspended?						(Yes or No)	
5. Al	5. Alarm logged in air monitoring action spreadsheet?						

Description of Action Taken:

No problems found during air monitor inspection. Weather may have contribute to the high particles readings. Air unit was recalibrated on 1/27/2020.