Ut.	IC CDF Dree	dge Projec	t : Air Mor	itoring Alar	m Response Log
Air Monitoring Station: Air Monitoring Instrument:	□ M1	区 M2	□ мз	□ M4	Dock
□ Cerex Unit (Naphthalene)				□ PID Mon	itor
Date & Time of alarm: 4/23/20 6:00 PM7: Email sent to site Technician?(Yes or No)Technician responded to the alarm? Scott Peterson					
 Was dredging occurring at the time of the alarm? Alarm caused by: 					(Yes or No))
Loss of Pow Loss of Rad	ver io Communicati	on			
Out of Calibration UV Alignment					
Blockage inAir QualityXOther: unknown					
 Corrective Actions tal 					(Yes or No))
4. Dredging suspended?5. Alarm logged in air monitoring action spreadsheet?					(Yes or No)

Description of Action Taken:

No problems found during air monitor inspection. Weather may have contribute to the high particles readings. Air unit was recalibrated on 4/24/2020.