IHC CDF Dredge Project : Air Monitoring Alarm Response Log					
Air Monitoring Station:	□ M1	区 M2	X M3	□ M4	□ Dock
Air Monitoring Instrument:□ Cerex Unit (Naphthalene)☑ Thermo Unit (Parti			rticles)	□ PID Monit	or
Date & Time of alarm: <u>6/23/202</u>	Email sent t	Email sent to site Technician? (Yes or No)			
 Technician responded to the ala 1. Was dredging occurring 2. Alarm caused by: 			(Yes or No)		
Loss of Power Loss of Radio Out of Calibra UV Alignmen Blockage in A Air Quality X Other: Unkno	Communicati ation at at air Tube	on			
 Corrective Actions take Dredging suspended? Alarm logged in air mo Description of Action Taken	nitoring actior	n spreadsheet?			(Yes or No) (Yes or No) (Yes or No)

Description of Action Taken:

Mowing sides of dike around air monitoring stations caused alarms.