IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring	Station:	X M1	□ M2	□ M3	□ M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (N	Vaphthalene)	X The	ermo Unit (Partic	cles)	☐ PID Monitor	
Date & Time of alarm: <u>8/24/2020 8:00 PM</u>				7: Email sent to	site Technician	(Yes or No)
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm? (Yes						(Yes or No)
2. Alarm caused by:						
	Loss of Power					
	Loss of Radio (Communication	1			
	Out of Calibrat	ion				
	UV Alignment					
Blockage in Air Tube						
	Air Quality					
X	Other: Unknow	'n				
						_
3. Corrective Actions taken?						(Yes or No)
4. Dredging suspended?						(Yes or No)
5. Alarm lo	5. Alarm logged in air monitoring action spreadsheet? (Yes) or No.					

Description of Action Taken:

No problems air monitor inspection. Weather may have contributed to the high particles' readings. Air unit was recalibrated on 8/15/2020.