IHC CDF Dredge Project : Air Monitoring Alarm Response Log \square M1 □ мз X M2 \Box M4 Dock **Air Monitoring Station: Air Monitoring Instrument:** Cerex Unit (Naphthalene) I Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: <u>9/3/2020 3:45 PM</u> (Yes or No) 7: Email sent to site Technician? Technician responded to the alarm? Scott Peterson (Yes or No) 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Х Blockage in Air Tube Air Quality Other: Unknown 3. Corrective Actions taken? (Yes or(No)) 4. Dredging suspended? (Yes or No) (Yes) or No) 5. Alarm logged in air monitoring action spreadsheet?

Description of Action Taken:

Insects were found in inlet tube. Vacuumed and cleaned inlet tube and re-calibrated air unit .