## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring S	tation:	□ M2	□ <b>M</b> 3	☑ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Na	aphthalene)	☑ Thermo Unit	(Particles)	☐ PID Monitor	
Date & Time of alarm: 11/14/2020 8:45 AM			7: Email s	ent to site Technician?	(Yes or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
I	Loss of Power				
I	Loss of Radio Commu	unication			
	Out of Calibration				
J 📄	UV Alignment				
I	Blockage in Air Tube				
I A	Air Quality				
X	Other: Unknown				
					_
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

## Description of Action Taken:

No problems noted during air monitor inspection. Weather may have contributed to the high particles' readings. Air unit was recalibrated on 11/14/2020.