## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Station	: □ M1	□ M2	☑ M3	□ M4	□ Dock
Air Monitoring Instrum	nent:				
☐ Cerex Unit (Naphthalene)			Particles)	☐ PID Mon	itor
Date & Time of alarm: <u>11/20/2020 3:00 PM</u>			7: Email se	nt to site Technici	an? (Yes or No)
Technician responded to	the alarm? Scott Po	eterson			
1. Was dredging occurring at the time of the alarm?					(Yes) or No)
2. Alarm caused by	:				
Loss of	Power				
Loss of	Loss of Radio Communication				
Out of	Calibration				
UV Ali	gnment				
Blockage in Air Tube					
Air Qu	ality				
X Other:	Unknown				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

## Description of Action Taken:

No problems noted during air monitor inspection. Weather may have contributed to the high particles' readings. Air unit was recalibrated on 11/21/2020.