## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring	<b>Station:</b>	□ M1	X M2	□ M3	□ M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene)			Thermo Unit (Pa	articles)	☐ PID Monito	or
Date & Time of alarm: <u>1/19/21 11:00PM</u>			Email sent	to site Technician?	(Yes on No)	
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Powe	er				
	Loss of Radio Communication					
	Out of Calibration					
	UV Alignment					
Blockage in Air Tube						
	Air Quality					
X	Other: Unkno	own				
<u> </u>						_
3. Corrective Actions taken?					(Yes) or No)	
4. Dredging suspended?					(Yes or No)	
5. Alarm lo	5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

## Description of Action Taken:

A) Unknown what caused the alarms. M2 air unit was checked and recalibrated.