IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Instrument: □ Cerex Unit (Naphthalene) □ Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: 3/02/21 9:30 -1:00 Email sent to site Technician? (Yes	or No.
	or(No)
Date & Time of alarm: 3/02/21 9:30 -1:00 Email sent to site Technician? (Yes	or No
	OLIVO
Technician responded to the alarm? Scott Peterson	
1. Was dredging occurring at the time of the alarm? (Yes of	r(No)
2. Alarm caused by:	
Loss of Power	
Loss of Radio Communication	
Out of Calibration	
UV Alignment	
Blockage in Air Tube	
Air Quality	
x Other: Unknown	
3. Corrective Actions taken? (Yes of	"(No)
· ·	
4. Dredging suspended? (Yes of	r (No))
5. Alarm logged in air monitoring action spreadsheet? (Yes)	r No)

Description of Action Taken:

A) Unsure of what caused the high particle readings. Air unit was checked, and calibration completed on 3/3/2021.