IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene)	\square	Thermo Unit (Pa	articles)	☐ PID Monito	or
Date & Time of alarm: 3/23/2	1 4:30PM		Email sent	to site Technician?	(Yes or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Powe	er				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
x Other: Unknown	own				
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

Description of Action Taken:

A) Unsure of what caused the high particle readings. Air unit was checked, and calibration completed on 3/24/2021.