## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Stati	ion:	□ M2	□ <b>M</b> 3	X M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Napht	thalene)	Thermo Unit (Partic	cles)	□ PID Monitor	r
Date & Time of alarm: <u>3/24/21-3/26/21</u>			Email sent to s	ite Technician?	(Yes on No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Los	s of Power				
Los	Loss of Radio Communication				
X Out	Out of Calibration				
UV	UV Alignment				
Blo	Blockage in Air Tube				
Air Quality					
Oth	er: Unknown				
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?				(Yes) or No)	

## Description of Action Taken:

A) Air Unit was out of calibration when checked. Air unit was checked, and calibration completed on 3/26/2021.