## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring	Station:	□ M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Partic			cles)	☐ PID Monito	r	
Date & Time of a	alarm: <u>4/8/21</u>			Email sent to si	te Technician?	(Yes or No)
Technician responded to the alarm? Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Power					
	Loss of Radio Communication					
X	Out of Calibrat	ion				
	UV Alignment					
	Blockage in Air Tube					
	Air Quality					
	Other: Unknow	/n				
						_
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?						(Yes)or No)

## Description of Action Taken:

A) Air Unit was out of calibration when checked. Air unit was checked and re-calibrated on 4/09/2021.