IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Mon	itoring	g Station:	□ M1	□ M2	□ M 3	☑ M4	□ Dock
Air Monitoring Instrument:							
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa					cles)	☐ PID Monito	r
Date & Time of alarm: <u>4/10/21</u>					Email sent to s	ite Technician?	(Yes or No)
Technician responded to the alarm? Scott Peterson							
1. V	1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:							
		Loss of Powe	er				
		Loss of Radio	o Communi	ication			
	X	Out of Calibr	ration				
		UV Alignme	nt				
		Blockage in A	Air Tube				
		Air Quality					
	X	Other: Unknown	own- readin	ng negative numbers			
							_
3. (3. Corrective Actions taken?						(Yes or No)
4. Г	4. Dredging suspended?						(Yes or No)
5. A	5. Alarm logged in air monitoring action spreadsheet?						(Yes) or No)

Description of Action Taken:

A) Air unit was out of calibration when checked. Air unit influent pipe was checked. Air unit was recalibrated on 4/11/2021.