## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station	: □ M1	□ M2	□ M3	☑ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa			articles)	☐ PID Monito	or
Date & Time of alarm: 5	/9/21 3:30 am	<u></u>	Email sent	to site Technician?	(Yes or No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of	f Power				
Loss of	Loss of Radio Communication				
Out of	Out of Calibration				
UV Al	UV Alignment				
Blockage in Air Tube					
Air Qu	Air Quality				
X Other:	Unknown- high rea	ading			
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

## Description of Action Taken:

A) Air unit was out checked. Air unit was re-calibrated on 5/10/2021.