## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring S	Station:	X M1	□ M2	□ M3	□ M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene)			☐ Thermo Unit (Particles)		☐ PID Monitor	
Date & Time of alarm: 10/11/2022 13:45-15:15						
Email sent to site Technician?				(Yes on No)		
Technician responded to the alarm? Scott Peterson						
2. Alarm cau		Communica tion t ir Tube	ū	time of the alarm?		(Yes or No)
	e Actions takes					(Yes or No)
<ol> <li>Dredging suspended? No dredging operation currently on site.</li> </ol>						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?						(Yes) or No)

## Description of Action Taken:

A) During the day thunderstorms with high winds caused the alarm. The air units were checked on the next day.