IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitorin	g Instrument:	Γhermo Scientific M	Model 5030 Sha	rp Monitor		
Air Monitorin	g Station:□ M1	□ M2	□ M3	□ M4	X AM1	X AM2
Date & Time of alarm: 10/01/2023 13:00						
X	Weekend					
	Non-Working H	ours				
	Active Contracti	ng On-Site				
	_					
Technician responded to the alarm:						
1. Alarm caused by:						
	Loss of Power					
	Loss of Radio C	ommunication				
	Loss of Cellular	connection				
	Out of Calibration	on				
	Air Quality, Tra	ffic, Site Maintenan	ce, Insects			
	Rain					
	Air Unit Malfun	ction				
X	Other					
2. Corrective Actions taken?						
	Fault Corrected					
X	Calibration com	pleted				
	Site activities sto	ppped				
X	Other					

Description of Action Taken: