IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Instrument: Thermo Scientific Model 5030 Sharp Monitor						
Air Monitoring	Station:□ M1	□ M2	□ M 3	□ M 4	□ AM1	☒ AM2
Date & Time of	alarm: <u>11/24/202</u>	3 16:30-19:45				
	Weekend					
	Non-Working I	Hours				
X	Active Contract	ing On-Site				
Technician respo		n:				
1. Marin Co	Loss of Power					
X	Loss of Radio (Communication				
	Loss of Cellula					
	Out of Calibration					
	Air Quality, Traffic, Site Maintenance, Insects					
	Rain					
	Air Unit Malfu	nction				
X	Other					
2. Corrective Actions taken?						
	Fault Corrected					
X	Calibration con	pleted				
	Site activities st	opped				
	Other					

Description of Action Taken:

A) It is unknown what is causing the communication failure maybe cellular or web site.